

Registration number

HW56 BLN



V5C

CJ 6031371

3/18



THIS DOCUMENT IS NOT PROOF OF OWNERSHIP.

It shows who is responsible for registering and taxing the vehicle.



Driver & Vehicle
Licensing
Agency

UNITED KINGDOM
UK REGISTRATION
CERTIFICATE

European Community


свидетелство за регистрација
Permiso de circulación
Osvědčení o registraci
Registreringsattest
Zulassungsbescheinigung
Registreerimistunnistus

Άδεια κυκλοφορίας /
Πιστοποιητικό Εγγραφής
Certificat d'immatriculation
Teastas Cláraithe
Carta di circolazione
Reģistrācijas apliecība

Registrācijas liudijimas
Forgalmi engedély
Certifikat ta' Reġistrazzjoni
Kentekenbewijs
Dowód Rejestracyjny
Certificado de matricula

Certificat de înmatriculare
Osvedčenie o evidencii
Prometno dovoljenje
Rekisteröintodistus
Registreringsbeviset
Prometna dozvola

1. Registered keeper



You must make sure that the name and address printed here is correct. If it is not, see section 12.

Document reference number

9010 845 3663

Thinking of buying this vehicle?

Buyer beware...

Do you know how to avoid being tricked into buying a stolen vehicle?

For tips and advice go to www.gov.uk/checks-when-buying-a-used-car

2. Data protection

DVLA handles your personal data in accordance with road vehicle law and data protection laws. The law allows us to release your data to the police and other enforcement bodies. We also provide data to other parties where the law allows it. For further information about how we process your data, your rights and who to contact, see our privacy notice at www.gov.uk/dvla/privacy-policy or request a written copy by phoning 0300 790 6106.

3. Special notes (these notes cannot be removed)

NO. OF FORMER KEEPERS 1

1. WAS REGISTERED AND/OR USED ELSEWHERE IN THE UK. DECLARED MANUFACTURED 2006.

10. New keeper's details – To be kept by the new keeper. Do not return to DVLA (see notes over the page)

Please tear along dotted line

V5C/2

Registration number **HW56 BLN** Validation character **5**

Please write new keeper's name and address in black ink

Write date of sale/transfer here

Postcode

Doc. Ref. No. **29010 845 3663**

Make **MERCEDES-BENZ**

Model

Colour **SILVER**

Engine size **2987 CC**

Suspension type

Tax class **DIESEL CAR**

No. of seats **5**

For specific information for this vehicle go to www.gov.uk/get-vehicle-information-from-dvla



Despatch Codes **292 / 1047991014 / 00129 31**

V5C2-0318

This will not produce a Registration Certificate.

11. Notification of permanent export – Please fill in and return to DVLA (see notes over the page)

Please tear along dotted line

V5C/4

V5C4-0318

1

Registration number **HW56 BLN** 2 Validation character **5** 3

Date of export

4

Document Ref. No. **9010 845 3663** 14 01 19

Despatch Codes **292 / 1047991014 / 00129 31**

This section will not produce an export certificate. The V5C replaces the need for a separate export certificate.

Declaration Please read the notes over the page before signing.

I declare that the vehicle will be exported on the date shown.

Signature: _____

Date: _____

12. What you need to know about the V5C and your responsibilities



Selling or transferring your vehicle privately

Vehicle tax or Statutory Off Road Notification (SORN) can't be passed on when a vehicle changes hands.

What you, the registered keeper must do.

- fill in section 6 (give the name and UK address of the new keeper)
- fill in section 10 (V5C/2) and give it to the new keeper
- notify DVLA of the sale/transfer online at www.gov.uk/sold-bought-vehicle or
- send the V5C to DVLA, Swansea, SA99 1BA

If you want to keep the registration number, you must do this before you sell/transfer it. You can do this online at www.gov.uk/keep-registration-number

What the new keeper/person buying the vehicle must do:

- keep section 10 (V5C/2) until they get their new V5C
- tax the vehicle immediately using section 10 (V5C/2).

What we will do:

- update our records with the new registered keeper details

- send you an acknowledgment letter within 4 weeks to confirm you are no longer liable for the vehicle, and issue an automatic refund of vehicle tax (if applicable) within 4-6 weeks. If you paid vehicle tax by Direct Debit, this will be cancelled.


If you do not get an acknowledgment letter or refund from us within the above time-scales you should contact us at www.gov.uk/contact-the-dvla as you could be liable for the vehicle and may get a penalty and/or be prosecuted.

Your name and/or address details.

- if the details in section 5 are wrong or you want to change your name or address, fill in section 6 and send the whole certificate to DVLA, Swansea, SA99 1BA. Do not tick the new keeper box. You should also make sure you tell us about these changes on your driving licence by sending it to DVLA, Swansea, SA99 1BN.

There is more information at www.gov.uk/vehicle-registration

Protect yourself from fraud. Potential buyers don't need the document reference number from your V5C to make checks. Don't share, keep it safe.



MERCEDES-BENZ

Registered vehicle details

Check the details below match the V5C logbook, vehicle appearance and vehicle information.

Make	MERCEDES-BENZ
Model	
Body type	ESTATE
Fuel type	HEAVY OIL
Transmission	AUTOMATIC 7 GEARS
Engine capacity	2987
VRM	HW56BLN
VIN	WDC1641222A150251
Engine number	642940402856
Colour	SILVER
Date first registered	01-06-2016
Year of manufacture	2006
Number of previous owners	1
Current V5C issue date	14-01-2019
CO2 emissions	254

Vehicle check report summary

Not recorded as stolen	<input checked="" type="checkbox"/>
Not recorded as scrapped	<input checked="" type="checkbox"/>
Not recorded as a write-off	<input checked="" type="checkbox"/>
Not imported	<input checked="" type="checkbox"/>
Not exported	<input checked="" type="checkbox"/>
No third-party interest	<input checked="" type="checkbox"/>
No outstanding finance	<input checked="" type="checkbox"/>
No mileage discrepancies	<input checked="" type="checkbox"/>
No colour changes	<input checked="" type="checkbox"/>
OTHER INFORMATION	
No recorded plate changes	<input checked="" type="checkbox"/>
No outstanding stocking finance	<input checked="" type="checkbox"/>
MOT expiry date	03-12-2025


Registered vehicle details & Vehicle check report summary

- Mileage data and V5C logbook data
- MOT record and Previous keepers
- Previous searches

This Vehicle Check report reflects information held against this vehicle on 11 September 2025.

Data is compiled from a number of sources and may take 24-48 hours to update. Please perform a new check after this period, if the data does still not reflect what you feel it should, then please contact support from Monday to Friday, 9am to 5pm.

Email
vehicle.check@autotrader.co.uk



MERCEDES-BENZ

MOT Information

Status	PASSED
MOT expiry	03-12-2025
Mileage recording	124,648

ADVISORY NOTICES

- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) ⓘ
- Oil leak, but not excessive (8.4.1 (a) (i)) ⓘ
- Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) ⓘ

HISTORIC TESTS

Most recent 10 of 14 MOT tests

Fail	124,624 mi	18-11-2024
Pass (1 advisories)	122,516 mi	20-11-2023
Pass (2 advisories)	116,906 mi	13-11-2022
Pass (11 advisories)	112,692 mi	19-11-2021
Fail	112,681 mi	18-11-2021
Pass (5 advisories)	107,354 mi	19-11-2020
Fail	107,354 mi	17-11-2020
Pass (4 advisories)	101,655 mi	20-11-2019
Fail	101,625 mi	18-11-2019

Previous keepers

Number of previous keepers	1
Date of last keeper change	20-11-2018

Registered vehicle details & Vehicle check report summary

Mileage data and VSC logbook data

MOT record and Previous keepers

Previous searches

This Vehicle Check report reflects information held against this vehicle on 11 September 2025.

Data is compiled from a number of sources and may take 24-48 hours to update. Please perform a new check after this period, if the data does still not reflect what you feel it should, then please contact support from Monday to Friday, 9am to 5pm.


Email
vehicle.check@autotrader.co.uk

GB **HW56BLN**

OUTCOME
ALL CHECKS PASSED 

MERCEDES-BENZ

Mileage data



RECORDINGS

Showing most recent 10 of 14 recordings

124,648	MOT	04-12-2024	112,681	MOT	18-11-2021
124,624	MOT	18-11-2024	107,354	MOT	19-11-2020
122,516	MOT	20-11-2023	107,354	MOT	17-11-2020
116,906	MOT	13-11-2022	101,655	MOT	20-11-2019
112,692	MOT	19-11-2021	101,625	MOT	18-11-2019

V5C logbook data

Current V5C issue date **14-01-2019**

- Registered vehicle details & Vehicle check report summary
- Mileage data and V5C logbook data**
- MOT record and Previous keepers
- Previous searches

This Vehicle Check report reflects information held against this vehicle on 11 September 2025.

Data is compiled from a number of sources and may take 24-48 hours to update. Please perform a new check after this period, if the data does still not reflect what you feel it should, then please contact support from Monday to Friday, 9am to 5pm.

Email
vehicle.check@autotrader.co.uk



Check MOT history

Help us make this service better. Give us your [feedback](https://www.smartsurvey.co.uk/s/GIZZX?vrm=HW56BLN&make_result=MERCEDES-BENZ&model_result=ML&mot_first_used_date=2006-12-31&vehicle_age=6829&mot_expiry_date=2025-12-03&mot_expiry_date_days_left=83&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) (https://www.smartsurvey.co.uk/s/GIZZX?vrm=HW56BLN&make_result=MERCEDES-BENZ&model_result=ML&mot_first_used_date=2006-12-31&vehicle_age=6829&mot_expiry_date=2025-12-03&mot_expiry_date_days_left=83&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

HW56 BLN

MERCEDES-BENZ ML

[Check another vehicle \(/\)](#)

Colour
Silver

Fuel type
Diesel

Date registered
31 December 2006

MOT valid until
3 December 2025

[Get an MOT reminder](https://www.gov.uk/mot-reminder) (https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates](/enter-document-reference?registration=HW56BLN) (/enter-document-reference?registration=HW56BLN)

You can [get information corrected on your MOT history](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

[↕ Hide all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[↕ Hide](#)

Date tested
4 December 2024

Mileage
124,648 miles

MOT test number
6070 2529 8281

PASS

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Expiry date
3 December 2025

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

▶ [What are advisories?](#)

Date tested
18 November 2024

Mileage
124,624 miles

MOT test number
3126 5187 0526

FAIL

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Repair immediately (major defects):

- **Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**
- **Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**
- **Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**

Repair as soon as possible (minor defects):

- **Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**
- **Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested
20 November 2023

Mileage
122,516 miles

MOT test number
6885 5088 5391

PASS

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3**

Expiry date
19 November 2024

**MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are advisories?](#)

Date tested
13 November 2022

PASS

Mileage
116,906 miles

Test location
**HALFORDS
AUTOCENTRES LTD
UNIT 1
MATRIX TRADE PARK
DARTFORD
DA1 5AJ**

MOT test number
3992 4419 1789

Expiry date
19 November 2023

Monitor and repair if necessary (advisories):

- **Central Rear brake lamp inoperative**
- **Central Front Oil leak, but not excessive advise attn to oil leaks (8.4.1 (a) (i))**

▶ [What are advisories?](#)

Date tested
19 November 2021

PASS

Mileage
112,692 miles

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

MOT test number
7010 6105 8569

Expiry date
19 November 2022

Repair as soon as possible (minor defects):

- **Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**
- **Nearside Side repeater insecure (4.4.1 (c) (i))**
- **Offside Front Brake hose slightly chafed & inadequately clipped (1.1.12 (b) (i))**
- **Nearside Front Brake hose slightly chafed & inadequately clipped (1.1.12 (b) (i))**
- **Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated slightly greasy (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Horn sounds slightly harsh**

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Rear Both brake discs slightly pitted on edges**

▶ [What are advisories?](#)

Date tested
18 November 2021

Mileage
112,681 miles

MOT test number
2115 0508 7595

FAIL

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Repair immediately (major defects):

- **Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**

Repair as soon as possible (minor defects):

- **Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**
- **Nearside Side repeater insecure (4.4.1 (c) (i))**
- **Offside Front Brake hose slightly chafed & inadequately clipped (1.1.12 (b) (i))**
- **Nearside Front Brake hose slightly chafed & inadequately clipped (1.1.12 (b) (i))**
- **Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated slightly greasy (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Horn sounds slightly harsh**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Rear Both brake discs slightly pitted on edges**

▶ [What are defects and advisories?](#)

Date tested
19 November 2020

PASS

Mileage
107,354 miles

MOT test number
4308 9785 9577

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Expiry date
19 November 2021

Monitor and repair if necessary (advisories):

- **Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Central Front Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are advisories?](#)

Date tested
17 November 2020

FAIL

Mileage
107,354 miles

MOT test number
4189 9174 5644

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

Do not drive until repaired (dangerous defects):

- **Nearside Front Tyre has ply or cords exposed inner edge showing ply (5.2.3 (d) (ii))**

Repair immediately (major defects):

- **Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**
- **Parking brake efficiency below requirements (1.4.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Central Front Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested
20 November 2019

PASS

Mileage
101,655 miles

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

MOT test number
4714 1429 5403

Expiry date
19 November 2020

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Rear Inner Tyre worn close to legal limit/worn on edge bold inner (5.2.3 (e))**
- **Nearside Front Tyre worn close to legal limit/worn on edge bold inner (5.2.3 (e))**
- **Brake disc worn, pitted or scored, but not seriously weakened both front discs (1.1.14 (a) (ii))**

▶ [What are advisories?](#)

Date tested
18 November 2019

FAIL

Mileage
101,625 miles

Test location
**FORMULA ONE
AUTOCENTRES
UNIT 2-3
MATRIX BUSINESS
CENTRE
DARTFORD
DA1 5AJ**

MOT test number
5314 2798 1118

Do not drive until repaired (dangerous defects):

- **Brake pad(s) less than 1.5 mm thick both front pads. (1.1.13 (a) (ii))**

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Rear Inner Tyre worn close to legal limit/worn on edge bold inner (5.2.3 (e))**
- **Nearside Front Tyre worn close to legal limit/worn on edge bold inner (5.2.3 (e))**
- **Brake disc worn, pitted or scored, but not seriously weakened both front discs (1.1.14 (a) (ii))**

▶ [What are defects and advisories?](#)

Date tested
20 November 2018

Mileage
91,591 miles

MOT test number
4114 9703 7813

PASS

Test location
GMS Kent Limited
UNIT 1
GIBRALTAR LANE
MAIDSTONE
ME14 2NG

Expiry date
19 November 2019

Date tested
14 November 2018

Mileage
91,587 miles

MOT test number
4507 5081 4884

FAIL

Test location
GMS Kent Limited
UNIT 1
GIBRALTAR LANE
MAIDSTONE
ME14 2NG

Repair immediately (major defects):

- **Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**
- **Offside Rear Direction indicator not working (4.4.1 (a) (ii))**
- **Oil leaking excessively from engine (8.4.1 (a) (i))**

▶ [What are defects?](#)

Date tested
23 June 2018

Mileage
90,839 miles

MOT test number
9763 3872 8034

PASS

Test location
GMS Kent Limited
UNIT 1
GIBRALTAR LANE
MAIDSTONE
ME14 2NG

Expiry date
22 June 2019

Monitor and repair if necessary (advisories):

- **Nearside Front wing repeater lens damaged**

▶ [What are advisories?](#)

Date tested
14 June 2018

Mileage
90,834 miles

MOT test number
7695 8219 0115

FAIL

Test location
GMS Kent Limited
UNIT 1
GIBRALTAR LANE
MAIDSTONE
ME14 2NG

Do not drive until repaired (dangerous defects):

- **Oil leaking continuously from engine posing a serious risk to road safety (8.4.1 (a) (ii))**

Repair immediately (major defects):

- **Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**
- **Rear Registration plate missing (0.1 (a))**
- **Front Registration plate insecure (0.1 (a))**

Monitor and repair if necessary (advisories):

- **Nearside Front wing repeater lens damaged**

▶ [What are defects and advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Check for vehicle recalls

See if MERCEDES-BENZ ML HW56BLN has outstanding recalls

⤴ Hide

No recalls found.

This information is provided by the vehicle manufacturer. If you think the recall information is wrong, contact your local MERCEDES-BENZ dealership.



[Cookies](#) [Terms and conditions](#) [Privacy notice](#)
[Accessibility statement](#) [MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

© [Crown copyright](#)

MOT test certificate

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

124,648 miles

Mileage history

122,516 miles

20.11.2023

116,906 miles

13.11.2022

112,692 miles

19.11.2021



Driver & Vehicle
Standards
Agency

⑦ Pass

Monitor and repair if necessary (advisories)

- Oil leak, but not excessive [8.4.1 (a) (i)]
- Brake disc worn, pitted or scored, but not seriously weakened Rear [1.1.14 (a) (ii)]
- Suspension arm pin or bush worn but not resulting in excessive movement Nearside Front [5.3.4 (a) (i)]

③b Date of the test

04.12.2024

⑧ Expiry date

03.12.2025

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 04.11.2025.

③a Location of the test

UNIT 2-3, MATRIX BUSINESS CENTRE, VICTORIA ROAD, DARTFORD, DA1 5AJ

⑨ Testing organisation and inspector name

**V110413 FORMULA ONE AUTOCENTRES
J. S. BANSAL**

MOT test number

6070 2529 8281

Duplicate certificate issued by DVSA on 11 September 2025

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

91,591 miles

Mileage history

90,839 miles 23.06.2018

⑦ **Pass**

③b Date of the test

20.11.2018

⑧ Expiry date

19.11.2019

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2019.

③a Location of the test

Unit 1, Gibraltar Lane, Maidstone Kent, ME14 2NG

⑨ Testing organisation and inspector name

**S000738 GMS Kent Limited
A. HARRIS**

MOT test number

4114 9703 7813

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

101,655 miles

Mileage history

91,591 miles 20.11.2018

90,839 miles 23.06.2018

⑦ **Pass**

Monitor and repair if necessary (advisories)

- Oil leak, but not excessive [8.4.1 (a) (i)]
- Tyre worn close to legal limit/worn on edge Nearside Rear Inner (bold inner) [5.2.3 (e)]
- Tyre worn close to legal limit/worn on edge Nearside Front (bold inner) [5.2.3 (e)]
- Brake disc worn, pitted or scored, but not seriously weakened (both front discs) [1.1.14 (a) (ii)]

⑧b Date of the test

20.11.2019

⑧ Expiry date

19.11.2020

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2020.

③a Location of the test

UNIT 2-3, MATRIX BUSINESS CENTRE, VICTORIA ROAD, DARTFORD, DA15AJ

⑨ Testing organisation and inspector name

**V110413 FORMULA ONE AUTOCENTRES
S. N. Aligwesa**

MOT test number

4714 1429 5403

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

Issuer signature

MOT test certificate

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

107,354 miles

Mileage history

101,655 miles 20.11.2019

91,591 miles 20.11.2018

90,839 miles 23.06.2018



Driver & Vehicle
Standards
Agency

⑦ Pass

Monitor and repair if necessary (advisories)

- Brake disc worn, but not excessively Nearside Front [1.1.14 (a) (i)]
- Brake disc worn, but not excessively Offside Front [1.1.14 (a) (i)]
- Brake pad(s) wearing thin Nearside Rear [1.1.13 (a) (ii)]
- Brake pad(s) wearing thin Offside Rear [1.1.13 (a) (ii)]
- Oil leak, but not excessive Central Front [8.4.1 (a) (i)]

③b Date of the test

19.11.2020

③c Expiry date

19.11.2021

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2021.

③a Location of the test

UNIT 2-3, MATRIX BUSINESS CENTRE, VICTORIA ROAD, DARTFORD, DA1 5AJ

⑨ Testing organisation and inspector name

**V110413 FORMULA ONE AUTOCENTRES
J. S. Clark**

MOT test number

4308 9785 9577

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

112,692 miles

Mileage history

107,354 miles 19.11.2020

101,655 miles 20.11.2019

91,591 miles 20.11.2018

⑦ Pass with defects

⑥ Repair as soon as possible (minor defects)

- Stop lamp(s) with a multiple light source up to 1/2 not functioning Central [4.3.1 (a) (i)]
- Side repeater insecure Nearside [4.4.1 (c) (i)]
- Brake hose slightly chafed Offside Front (& inadequately clipped) [1.1.12 (b) (i)]
- Brake hose slightly chafed Nearside Front (& inadequately clipped) [1.1.12 (b) (i)]
- Drive shaft joint constant velocity boot severely deteriorated Nearside Front Outer (slightly greasy) [6.1.7 (g) (i)]

Monitor and repair if necessary (advisories)

- (Horn sounds slightly harsh)
- Oil leak, but not excessive [8.4.1 (a) (i)]
- Tyre worn close to legal limit/worn on edge Nearside Rear [5.2.3 (e)]
- Brake pipe corroded, covered in grease or other material Nearside Rear [1.1.11 (c)]
- Brake pipe corroded, covered in grease or other material Offside Rear [1.1.11 (c)]
- Rear (Both brake discs slightly pitted on edges)

③b Date of the test

19.11.2021

③ Expiry date

19.11.2022

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2022.

③a Location of the test

UNIT 2-3, MATRIX BUSINESS CENTRE, VICTORIA ROAD, DARTFORD, DA1 5AJ

⑨ Testing organisation and inspector name

**V110413 FORMULA ONE AUTOCENTRES
S. MAHMOOD-SIDDIQ**

MOT test number

7010 6105 8569

Issuer signature

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

116,906 miles

Mileage history

112,692 miles 19.11.2021

107,354 miles 19.11.2020

101,655 miles 20.11.2019

⑦ **Pass**

Monitor and repair if necessary (advisories)

- Central Rear (brake lamp inoperative)
- Oil leak, but not excessive Central Front (advise attn to oil leaks) [8.4.1 (a) (i)]

③b Date of the test

13.11.2022

⑧ Expiry date

19.11.2023

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2023.

③a Location of the test

UNIT 1, MATRIX TRADE PARK, VICTORIA ROAD, DARTFORD, DA1 5AJ

⑨ Testing organisation and inspector name

V110404 HALFORDS AUTOCENTRES LTD

E. D. ARNOLD

MOT test number

3992 4419 1789

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

122,516 miles

Mileage history

116,906 miles 13.11.2022

112,692 miles 19.11.2021

107,354 miles 19.11.2020

⑦ **Pass**

Monitor and repair if necessary (advisories)

- Oil leak, but not excessive [8.4.1 (a) (i)]

③a Date of the test

20.11.2023

③b Expiry date

19.11.2024

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 20.10.2024.

③c Location of the test

UNIT 2-3, MATRIX BUSINESS CENTRE, VICTORIA ROAD, DARTFORD, DA1 5AJ

⑨ Testing organisation and inspector name

**V110413 FORMULA ONE AUTOCENTRES
J. S. BANSAL**

MOT test number

6885 5088 5391

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WDC1641222A150251

②a Registration number

HW56BLN

②b Country of registration

GB

Make and model

MERCEDES-BENZ ML

⑤ Vehicle category

M1

④ Mileage

90,839 miles

⑦ **Pass**

Monitor and repair if necessary (advisories)

- Nearside Front (wing repeater lens damaged)

③b Date of the test

23.06.2018

⑧ Expiry date

22.06.2019

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 23.05.2019.

③a Location of the test

Unit 1, Gibraltar Lane, Maidstone Kent, ME14 2NG

⑨ Testing organisation and inspector name

**S000738 GMS Kent Limited
A. HARRIS**

MOT test number


9763 3872 8034

Duplicate certificate issued by DVSA on 11 September 2025

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.



Mercedes-Benz
Service Booklet

HWS6 3LN



Mercedes-Benz

Vehicle data

▶ MERCEDES

Model

▶ ML270

Registration number

▶ HW56 BLN

Registration number

▶ WDC1G41222A1J0257

Vehicle identification number

▶ NKAAAF01

Registration number

▶

Registration number

▶

Initial registration

▶

Registration number

▶

Registration number

▶

SILVER

Paintwork

▶

—

Registration number

▶

—

Registration number

Service reports

ML320 Full Service
 Vehicle identification number

29-09-2008
 Date

3702
 Repair job no.

16,721
 Odometer reading

MobiloLife: Yes No

Mobility Yes No

Warranty against rusting from the inside Yes No

(until the next service is due)

ASSYST PLUS

Workshop code

Remaining distance
 in km / miles

Remaining time in days

Engine oil brand

Viscosity

—
 —
 Shell 30

Replaced /
 renewed:

Engine oil

Fuel Filter

Coolant

Activated charcoal filter

Combination filter

Yes No

Yes No

Spark plugs

Air cleaner

Brake fluid

Poly-V-belt

Dust filter


 Signature / stamp of Mercedes-Benz Service Centre

Confirmations

Service reports

MINOR (ML370)

Vehicle identification number

702

Repair job no.

15 / 10 / 2010

Date

30 - 784

Odometer reading

MobiloLife:

Yes No

Mobility

Warranty against rusting from the inside

(until the next service is due)

Replaced / renewed:

Yes No

Engine oil

Spark plugs

Yes No

Fuel Filter

Air cleaner

Coolant

Brake fluid

Activated charcoal filter

Poly-V-belt

Combination filter

Dust filter

ASSYST PLUS

Workshop code

Remaining distance
in km / miles

Remaining time in days

Engine oil brand

Viscosity

Signature / stamp of Mercedes-Benz Service Centre

AUTOS
 MECHANIC
 SERVICE & REPAIRS
 TEL: 011 428 4284

Service reports

Full Service ML320
 Vehicle identification number

16-06-2011
 Date

NEXT OLE 42k miles
 Repair job no.

32-078
 Odometer reading

MobilLife: Yes No

Mobility Yes No

Warranty against rusting from the inside Yes No

(until the next service is due)

ASSYST PLUS

no
 Workshop code

Replaced /
 renewed:

Yes No

Yes No

Engine oil Spark plugs

Fuel Filter Air cleaner

Coolant Brake fluid

Activated charcoal filter Poly-V-belt

Combination filter Dust filter

Remaining distance:
 in km / miles

Remaining time in days

Engine oil brand

Viscosity

Delux BD's 10708 + km
 MOBILE MECHANIC
 SERVICING & REPAIRS
 TEL: 07331 09842

Signature / stamp of Mercedes-Benz Service Centre

Confirmations

Service reports

HWS6 BLN SILVER

Vehicle identification number

22.08.2013

Date

MINOR SERVICE

Repair job no.

41.700

Odometer reading

MobilLife:

Yes No

Mobility

Warranty against rusting from the inside

(until the next service is due)

Replaced /
renewed:

Yes No

Yes No

Engine oil

/

Spark plugs

/

Fuel Filter

/

Air cleaner

/

Coolant

/

Brake fluid

/

Activated charcoal filter

/

Poly-V-belt

/

Combination filter

/

Dust filter

/

ASSYST PLUS

Workshop code

Remaining distance
in km / miles

Remaining time in days

Engine oil brand

Viscosity

Full IDA AUTOS
MOBILE MECHANIC
SERVICING & REPAIRS
TEL: 07431 22842

Signature / stamp of Mercedes-Benz Service Centre

Service reports

30 Mercedes 320
 Vehicle identification number

Full service carried out
 Repair job no.

29-10-2015
 Date

82,900
 Odometer reading

MobiLife:

Yes No

Mobility

Warranty against rusting from the inside

(until the next service is due)

62k miles

ASSYST PLUS

Workshop code

Remaining distance
 in km / miles

Remaining time in days

Engine oil brand

Viscosity

Replaced /
renewed:

Yes No

Engine oil

Fuel Filter

Coolant

Activated charcoal filter

Combination filter

Yes No

Spark plugs

Air cleaner

Brake fluid

Poly-V-belt

Dust filter

INTAS
 LUBRICANTS
 OILS & REPAIRS
 42842

Signature / stamp of Mercedes-Benz Service Centre

Service Booklet

Confirmations

Service reports

ML230 HW56 BLN
Vehicle identification number

06 11 2016
Date

MINOR SERVICE
Repair job no.

72,829
Odometer reading

MobilLife:

Yes No

Mobility

Warranty against rusting from the inside

(until the next service is due)

ASSYST PLUS

Workshop code

Remaining distance
in km / miles

Remaining time in days

Engine oil brand

Viscosity

Replaced /
renewed:

Yes No

Engine oil

/

Spark plugs

Yes No

/

Fuel Filter

/

Air cleaner

/

Coolant

/

Brake fluid

✓

Activated charcoal filter

/

Poly-V-belt

✓

Combination filter

/

Dust filter

✓

BDS AUTOS
MOBILE MECHANIC
SERVICING & REPAIRS
TEL: 07431142842

Signature / stamp of Mercedes-Benz Service Centre

Service reports

Vehicle identification number

23 - 09 - 2008
Date

Repair job no.

91,002
Odometer reading

MobiloLife:

Yes No

Mobility

Warranty against rusting from the inside

(until the next service is due)

ASSYST PLUS

Workshop code

Replaced /
renewed:

Yes No

Engine oil

Spark plugs

Yes No

Fuel Filter

Air cleaner

Coolant

Brake fluid

Activated charcoal filter

Poly-V-belt

Combination filter

Dust filter

Remaining distance
in km / miles

Remaining time in days

Engine oil brand

Viscosity

Autotech Kent Car Sales
(Cranbrook Ltd)
Forstal Cottages
Aylesford, ME20 7HB
01622 710299

Signature / stamp of Mercedes-Benz Service Centre



INVOICE

GRAVESEND (182)
 Unit D1,
 Imperial BusinessPark
 West Mill
 London Road
 Gravesend Kent
 DA11 0DG
 Tel:01474 355 000
 Fax:01474 360 444
 Vat:GB766436989

GRAVESEND Retail Counter
 Unit D1, Imperial Business Park
 London Rd
 West Mill
 Gravesend
 DA11 0DL
 01474 355 000
 Customer VAT number:

WEE/HB2719VY - NPWD:231839 - BPRN:00598

Deliver To	SLA	Date	Time	Customer Ref.	
GRAVESEND Retail Counter Unit D1, Imperial Business Park London Rd West Mill Gravesend DA11 0DL 01474 355 000	C	17/05/2025	10:11	HW568LN	
	Delivery Area	Reference No.	Codes	Invoice No.	Branch
	C	514489	kirkros	04401415	182
	Picked By	Customer No.	Invoice Type	Page No.	
		E6000490		CASH	1

Line	Qty	Part No.	Bin	Description	Weight KG	List Price	VAT	Unit Price	Net Total
1	1	333 22 0061	22G08	SUMP PLUG MERCEDES107 114 11	0.03	2.40	S	4.29	3.57
		Customer Part:	31000957						
2	1	501 22 0287	22K10	F026 407 008 (BOSCH) OIL FIL	0.07	13.50	S	12.99	10.82

Rate	Goods	Vat	Plastic	Subtotal	
20.000 s	14.40	2.88	17.28		14.40
				Vat	2.88
				Total (GBP)	17.28

Adhoc Returns will soon be handled digitally, no longer on paper. Please call the branch to arrange a collection for large qty's of returns.

Branch Open 08:00 to 18:00 Monday - Friday and 08:00 to 16:00 Saturday

LKQ Euro Car Parts is a trading name of LKQ Group (UK) Limited. LKQ Group (UK) Limited is registered in England & Wales (Company No 02680212).

Registered office: T2, Birch Coppice Business Park, Danny Morson Way, Dordon, Tamworth, England, B78 1SE. VAT No: 766436989. All purchases

made are subject to our standard terms and conditions, a copy of which can be viewed at corporate.eurocarparts.com/terms-and-conditions or may be requested at branch.

Formula one autocentres

Unit 2, Matrix Trade Park
 Victoria Road, Dartford
 DA1 5AJ,
 Tel: 01322 277770
 Email: 085@f1autocentres.com

Invoice

For T&Cs please see website

Customers Address :

[REDACTED]

Document No : 085I223661
 Date & Time : 19/11/2020 15:15
 Account No :
 Mileage : 107354
 Vehicle Reg : HW56BLN
 Vehicle : Mercedes Benz, M Class ML320
 Page No : 1 of 2
 Operator : FC085
 Order No :

Labour	VAT%	Net Total
1 Hours Labour TO REPLACE THE OSF STEERING RACK GATOR	20.0	58.33
1 Hours Labour TO STRIP DOWN, CLEAN AND ADJUST REAR DRUM HANDBRAKE	20.0	58.33
Labour Sub Total		116.66

Parts	Qty	Unit	VAT%	Net Total
255 50 19 V Budget Tyre 107V XL {4x4} Fuel Eff : F. Wet Grip : F. Noise : 72 dB	1.00	54.29	20.0	54.29
Tyre Disposal Charge**	1.00	1.93	20.0	1.93
Wheel Balance	1.00	6.66	20.0	6.66
Sundries	1.00	3.06	20.0	3.06
Steering Rack Gaiter	1.00	18.64	20.0	18.64
Parts Sub Total				84.58

Advisory Notes:

VEHICLE SUFFERS WITH POOR STARTING AND OILY COOLANT LEAK



Account No. HOAW406247
 Job No. 085J227360
 Quote No.
 Technician Tom Lyne

VAT Reg No: GB 307 580 604
 Company Reg No: 1437311

Net Total	£	201.24
VAT Value	£	40.26
Invoice Total	£	241.50

Paid (Credit Card:241.50), 19/11/2020

Order Confirmation

- | Your **Click & Collect** order details are as follow -



Order Ref no:123-00050368459

Placed at:09:19 am, NOV 15, 2021

Dear Customer,

Thank you for your order. Your items will be ready to collect at our **Gravesend** collection point from **10:00 am on Tuesday 16, November**. Your click and collect order will be available for 6 working days from the day of booking. Please bring a copy of your confirmation email or your order reference with you as proof of reservation.

Invoice to:



Collection Point:

Gravesend Collection Point
Euro Car Parts
Unit D1, Imperial Business Park
London Rd
West Mill
Gravesend
DA11 0DL

Qty	Parts	Description	Vehicle	Reg	Price
2	104221319	Eicher Premium Brake Disc (Front)	Mercedes-Benz M Class 3.0 2006	HW56 BLN	£114.06
1	101220929	Eicher Premium Brake Pad (Rear)	Mercedes-Benz M Class 3.0 2006	HW56 BLN	£31.94
Subtotal					£146.00
Collection Charge					£1.99
Coupon Discount					- £29.21
Grand Total					£118.78

Collection Point Details

Gravesend Collection Point

Euro Car Parts
Unit D1, Imperial Business Park
London Rd
West Mill
Gravesend
DA11 0DL

Opening Hours

Mon 08:00am-06:00pm
Tue 08:00am-06:00pm
Wed 08:00am-06:00pm
Thu 08:00am-06:00pm
Fri 08:00am-06:00pm
Sat 08:00am-04:00pm
Sun Closed

Please note that these opening times are updated regularly but may change due to unforeseen circumstances





Mercedes-Benz Dartford

CASH SALE INVOICE

Invoice Name & Address Parts Retail Cash Sales Dartford ** Update with customer details *****	Page No. 1	Customer Name & Address Parts Retail Cash Sales Dartford ** Update with customer details ** *****
---	---------------	---

You were served by: Darren Bailes Van: Inv by: 2225

Model	Chassis No.	Engine No.	Reg Date.	Reg No.
Account No.	Customer Order No	VSF No.	Dept	Selling Dealer
C2201	WDC1641222A150251		P	
Colour	Date Last Visit	Date In	Date Due Out	Time Due Out
		17/11/2021		15:14

Special order and Electrical parts cannot be returned.
 Other returns may be subject to a handling charge of 20%

Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
P MA220 421 01 71 10020173 BRK DISC BOLT	2	2.10	EACH 18	4.20	S

Parts	4.20	V	Rate	Goods/Service	V.A.T.	Net	£	4.20
Surcharge	0.00	S	20.00	4.20	0.84	VAT	£	0.84
Labour	0.00					Total	£	5.04
Sublet	0.00					Paid	£	0.00
Menus	0.00					Owing	£	5.04

Mercedes-Benz Dartford Unit 1 Rennie Drive Dartford DA1 5FD Telephone: 01322 294414

Website: www.mercedes-benzretailgroup.co.uk Email: internet.enquiries@daimler.com

VAT Reg. No. GB 225 0270 08 Registered in England 419087 Registered Office: Mercedes-Benz Retail Group UK Limited Tongwell Milton Keynes MK15 8BA



INVOICE

CP4L Pay Online Collect Instore O&C
GRAVESEND

Gravesend Kent

Tel:

Fax:01474 360 444

Vat: GB766436989

16/11/2021	17:03	123-00050368459			
MO	886205	ITNET	1820017861	182	
	E4280182	CASH		1	

Line	Qty	Part no.	Bin	Description	List Price	VAT	Unit price	Net Total
1	1	CNC-CP4L		Collection Charge		S	1.99	1.66
2	1	101220929	22M10	Eicher Premium Brake Pad _{Tá} (Rear	126.00	S	25.55	21.29
3	2	104221319		CROSS D Eicher Premium Brake Disc _{Tá} (Fro	72.07	S	45.62	76.03

Additional information :-

T1PZ6B

Subtotal	98.98
Vat	19.80
Total (GBP)	118.78

Branch Open 08:00 to 18:00 Monday - Friday and 08:00 to 16:00 Saturday

Formula one autocentres

Unit 2, Matrix Trade Park
Victoria Road, Dartford
DA1 5AJ,
Tel: 01322 277770
Email: 085@f1autocentres.com

Invoice

For T&Cs please see website

Customers Address :

Mr . FORMULA ONE INTERNET SALES

Document No : 085I222624
Date & Time : 09/09/2020 09:40
Account No : F1001
Mileage : 106009
Vehicle Reg : HW56BLN
Vehicle : MERCEDES-BENZ, ML320
Page No : 1 of 2
Operator : FC085
Order No : WEB40076978

Parts	Qty	Unit	VAT%	Net Total
Sundries	1.00	3.06	20.0	3.06
Wheel Balance	1.00	6.66	20.0	6.66
Tyre Disposal Charge**	1.00	1.28	20.0	1.28
255 50 19 V Budget Tyre 107V XL {4x4}	1.00	53.92	20.0	53.92
Parts Sub Total				64.92

Advisory Notes:

OSR TYRE

LOCKER CENTER CONSOL

Account No. F1001
Job No. 085J226144
Quote No.
Technician Anthony Salsbury

VAT Reg No: GB 307 580 604
Company Reg No: 1437311

Net Total	£	64.92
VAT Value	£	12.98
Invoice Total	£	77.90



INVOICE

CRAYFORD (76)
 Unit 14/15 Optima Park
 Thomas Road - off Thames Road
 Crayford
 Kent

CLICK & COLLECT
 CRAYFORD

DA1 4GA
 Tel:01322 315000
 Fax:01322 553123
 Vat:766 4369 89

Customer VAT number:

Deliver To	SLA	Date	Time	Customer Ref.	
	C	18/11/2019	17:17	10118243	
	Delivery Area	Reference No.	Codes	Invoice No.	Branch
	C	482500	ITNET	08341107	76
	Picked By	Customer No.	Invoice Type	Page No.	
		11000044	CASH	1	

Line	Qty	Part No.	Bin	Description	List Price	VAT	Unit Price	Net Total
1	1	101220919	22F09	Eicher Premium Brake Padá(Fron	67.33	S	25.84	21.53

Additional information :-
 early19
 **** Collection Only ****

Rate	Goods	Vat	Credit Card PDQ	Subtotal	21.53
20.000 S	21.53	4.31	25.84	Vat	4.31
				Total (GBP)	25.84

Branch Open 08:00 to 18:00 Monday - Friday and 08:00 to 16:00 Saturday

All purchases made, whether under the brand name LKQ Coatings or otherwise are subject to Euro Car Parts standard terms & conditions of sale which can be requested in-store & found online at corporate.eurocarparts.com/terms-and-conditions. All goods and services are provided by Euro Car Parts Limited. Registered office: Euro House, Fulton Road, Wembley Industrial Estate, Wembley, Middlesex, HA9 0TF. Company no: 2680212. Contact: 0845 603 3636.